

TFCU Electro Box Rework PASS 2018-0171

Unit models: 42GW-42N-42NH-NL Build date: From March 2017 to October 2018

Problem Description

The electro box's plastic casing material is not compliant with Carrier flammability resistance requirements. If a fire occurs, the plastic casing of the electro box doesn't contain the fire as expected.

QUAL information bulletin

BRN 1902 07/2019

MANDATORY ACTION



DETAILS

Affected units

- > Product range: Terminal fan coils
- Models: TFCU 42GW-42N-42NH-42NL
- > Manufacturing site: Beroun, Czech Republic

Rework procedure

> The current electro box (black color) will be replaced by a new one (grey color).

- Parts to be ordered directly from ERCD:
 - 00PSG003203800A : Small box 42GW-42NH/NL; 5.1€
 - 00PSG003203900A : Large box 42GW; 6.75€
 - 00PSG003204000A : Small box with insulation 42N; 6.15€
 - 00PSG003204100A : Large box with insulation 42N; 7.2€
 - Please scrap the old black electro box responsibly
- Follow the rework instructions and IOM

> Labels: If possible, remove the electrical labels from the black electro box and stick them on the new grey electro box. If the labels don't come off, have the following kit labels handy (ordered from ERCD)

- 00PSP000000496A : Kit Labels 42N (13.8€, set of 50 labels)
- 00PSP000000497A : Kit Labels 42GW Large box (12€, set of 50 labels)

> Update your rework tracking database

Documentation

- > Rework instructions for small & large electro boxes
- > WeWITS reimbursement process
- > IOM

Service limit time

> This safety related rework must be handled as a priority and completed as soon as possible.

Allowance

- > 45€ per unit all inclusive
- Reimbursement claims to submit in WeWITS

FOR ACTION

> Units:

> Limit time:

List of units provided

No end date

Warning: Do not perform any servicing instructions in this Flash unless you are a trained, qualified technician. Follow all safety precautions, equipment tags, labels and all other applicable safety precautions. Failure to do so could result in property damage, personal injury or death.

Ref: FQ BRN 1902- 07/2019 Originated by: Miguel Zamora / Contact: tfcu.retrofit@carrier.com/ Department: Quality Internal correspondence / **Company private**